
PREPARED BY: TYPE: PROJECT:



# SEAMLESS LINKABLE **LED LUMINARY** RIB AC





### **SPECIFICATIONS**

70LM/W IP20 Lumen Enviornment Wattage 3W/FT Warranty 5 Year Input Voltage 120V Dimming Triac 2700K, 3000K, 3500K, 4000K, 5000K SMD 2835 Color Temperature Chip Certification Beam Angle UL, CE Application Surface Mount, Recessed Max Run 39.4FT -20°- 45C° CRI 90 Operating Temperature















RIBAC - \_\_\_\_ - 120V - \_\_\_\_ Example: RIBAC-4-27K-120-BK


MODEL	Length	Wattage	Lumens	Color Temperature	Voltage		Finish
RIBAC	<b>4</b> 4IN	1VV	70LM	<b>27</b> 2700K		WT	White
	6 6IN 8 6IN	1.5W 2W	110LM 140LM	<b>30</b> 3000K		ВК	Black
	<b>12</b> 12IN	3W	210LM	<b>35</b> 3500K	120V	BN	Brushed Nickel
	<b>24</b> 24IN <b>48</b> 48IN	6W 12W	420LM 840LM	<b>40</b> 4000K		GD	Gold
				<b>50</b> 5000K			

**REVISION DATE 12/2/2023** TELEPHONE: 212.931.1230 SUPPORT@RAYHIL.COM WWW.RAYHIL.COM PROJECT: PREPARED BY: TYPE



# SEAMLESS LINKABLE LED LUMINARY RIB AC

### **ACCESSORIES**





Juction box

### **ORDERING GUIDE**

## RIBAC - \_\_\_\_\_ Example: RIBAC-EC

MODEL	TYPE	DESCRIPTION
RIBAC	EC PP C 40-S MC MNT JB C2 PPBF 40-SBF	Extender Connector Power Plug 40 Inch Straight feed 12 Inch Coupling 40inch Starter Straight feed Mounting Clip Magnet Set Junction box with 40inch Starter 2 Inch Coupling Power Plug Bottom Feed 40 Inch Starter Bottom Feed


REVISION DATE 12/2/2023 TELEPHONE: 212.931.1230 SUPPORT@RAYHIL.COM WWW.RAYHIL.COM

PROJECT: PREPARED BY: TYPE:



# SEAMLESS LINKABLE LED LUMINARY RIB AC

### **DIAGRAM**



REVISION DATE 12/2/2023 TELEPHONE: 212.931.1230 SUPPORT@RAYHIL.COM WWW.RAYHIL.COM




# SEAMLESS LINKABLE LED LUMINARY RIB AC


#### **INSTALLATION**

Option 1: Fixed by magnet.


Magnet on backside is embedded inside the PC housing.




Directly stick to the metal mounting surface.




Option 2: Fixed by magnet and metal sheet.




Fix the metal sheet by screw according to the position of the magnet firstly, and then stick the product to the metal sheet.




Option 3: Fixed by adhesive tape.






Option 4: Fixed by bracket.



Fix the bracket to the mounting surface by screw firstly, and then clip the product into the bracket.



REVISION DATE 12/2/2023 TELEPHONE: 212.931.1230 SUPPORT@RAYHIL.COM WWW.RAYHIL.COM